

Misrepresentation of Intertek Certified Product / Représentation erronée du produit certifié Intertek

45 Minute Fire Door and Frame

Notification Type:	Misuse of Certification Mark
Certification Type:	Not Intertek Certified

Notification

Intertek notifies public that we have been notified by the applicant that the labels identified below have been misrepresented as Intertek Certified. / Intertek informe le public que le demandeur nous a informés que les étiquettes identifiées ci-dessous ont été présentées à tort comme étant certifiées Intertek.

Company Identification

CP Distributors & AccessSMT Holdings Winnipeg

Product Identification

A misrepresentation of certified product labels for CP Distributors & AccessSMT Holdings Winnipeg using W/N 00316 qty 100 (SN 45401-45500) and W/N 00310 qty 200 (SN 44801-45000) lost labels, See photos on page 2.

Product: Fire Door Frame
Name: CP Distributors Ltd. (Calgary, AB)
Address: 120-4550 25 St., S.E., Calgary, AB T2B 3P1
PO# for label order that was lost: PO090438
W/N 00316 qty 100 (SN 45401-45500)
Label Description: 45 Minute Frame (C & US)- NFPA 252 UL 10b CAN/ULC S104 (METAL)

Product: Fire Door
Name: AccessSMT Holdings Ltd. (Unit E, 1725 Inkster Blvd., Winnipeg, MB)
Address: Unit E, 1725 Inkster Blvd., Winnipeg, MB R2X 1R3
PO# for label order that was lost: PO090408
W/N 00310 qty 200 (SN 44801-45000)
Label Description: 45 Minute Door (C & US)- NFPA 252 UL 10b CAN/ULC S104 (METAL)

Hazard Involved

Not Intertek Certified.

What To Do

Use should be immediately discontinued and return to the point of purchase. Distributors and retailers should discontinue sales and return inventories to their suppliers.
/ L'utilisation doit être immédiatement interrompue et revenir au point d'achat. Les distributeurs et les détaillants doivent cesser les ventes et retourner les inventaires à leurs fournisseurs.

Published: July 28, 2026
Revised:

Public Notice ID: PN-2026-431
Page 2 of 2

Photos and Images

Product: Fire Door Frame
Name: CP Distributors Ltd. (Calgary, AB)
Address: 120-4550 25 St., S.E., Calgary, AB T2B 3P1
PO# for label order that was lost: PO090438
W/N 00316 qty 100 (SN 45401-45500)
Label Description: 45 Minute Frame (C & US)- NFPA 252 UL 10b CAN/ULC S104 (METAL)



Product: Fire Door
Name: AccessSMT Holdings Ltd. (Unit E, 1725 Inkster Blvd., Winnipeg, MB)
Address: Unit E, 1725 Inkster Blvd., Winnipeg, MB R2X 1R3
PO# for label order that was lost: PO090408
W/N 00310 qty 200 (SN 44801-45000)
Label Description: 45 Minute Door (C & US)- NFPA 252 UL 10b CAN/ULC S104 (METAL)

